

## Department of Environmental Quality

Northwest Region Portland Office 2020 SW 4<sup>th</sup> Avenue, Suite 400 Portland, OR 97201-4987 (503) 229-5263 FAX (503) 229-6945 TTY (503) 229-5471

August 26, 2002

John Edwards Anchor Environmental, Inc. 6650 SW Redwood Lane, Suite 110 Portland, Oregon 97224

RE: Non-Aqueous Phase Product

Brix Maritime Site Portland, Oregon ECSI No. 2364

## Dear John:

This letter documents our August 22, 2002 telephone conversation regarding the discovery of non-aqueous phase liquid (NAPL) at the Brix Maritime facility. Based on our conversation, I understand that the product was detected in monitoring well MW-3 during routine groundwater elevation monitoring activities.

As a result of this discovery, DEQ requested the following activities be performed:

- Collect a sample of the NAPL for fuel fingerprinting. Based on this result, additional analyses may be required (for example, polycyclic aromatic hydrocarbons and volatile organic compounds).
- Inspect the riverfront near MW-3 for potential NAPL seeps.
- Delineate the extent of the NAPL during future well installation activities.

In addition, DEQ requests that Brix obtain monthly product thickness measurements and perform monthly beach inspections and report the results to DEQ within two (2) weeks of the field event. Please provide the results of the NAPL testing and beach inspections within 30-days of this letter. If you have any questions, please call me at (503)229-5562 or email me at rodney.struck@deq.state.or.us.

Sincerely,

Rodney G. Struck, R.G.

Project Manager

Cleanup and Portland Harbor Program

Cc: Kim Johannessen, Johannessen & Associates

David Templeton, Anchor Environmental, Inc., Seattle

Frank Williamson, Foss

Bruce Brody-Heine, DEQ CU/PH

ECSI File No. 2364

